



AMP GAS CONVERSION KITS

Field Conversion Kits: To Natural Gas

MODEL	PART NUMBER To Natural Gas	Description	Qty.
400	111545-01	Kit includes:	
	106096-01	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	1
	107694-01	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	1
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	109548-08	Mixer, Lamp 400, Hm140 Ng, Dn 38, 400 Mbh Polidoro 350.0970.02	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110502-01	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	3
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
	500	111545-02	Kit includes:
106096-01		1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	1
107694-01		O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	1
108161-01		Warning Card, Blower Outlet Gasket Installation	1
109548-07		Mixer, Lamp500, Hm150 Ng, Dn 42-44, 12:00 Polidoro 350.0971.04	1
110301-01		Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
110502-01		M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	3
112068-11		Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
81960109		Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
650		111545-03	Kit includes:
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	109548-06	Mixer, Lamp 650, Hm500 Ng, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.04	1
	110056-02	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
	110202-01	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110501-03	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	4
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
	800	111545-04	Kit includes:
108161-01		Warning Card, Blower Outlet Gasket Installation	1
109548-05		Mixer, Lamp 800, Hm500 Ng, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.02	1
110056-02		Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
110202-01		O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
110301-01		Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
110501-03		M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	4
112068-11		Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
81960109		Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
1000L		111545-05	Kit includes:
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	109548-04	Mixer, Lamp 1000, Hm500 Ng, Dn 55, 1000Mbh, 140Bc Polidoro	1
	110056-02	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
	110202-01	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110501-03	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	4
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1

Field Conversion Kits: To LP Gas

MODEL	PART NUMBER To LP Gas	Description	Qty.
400	111544-01	Kit includes:	
	106096-01	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	1
	107694-01	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	1
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110502-01	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	1
	111054-01	Mixer, Lamp 400, Hm140 Lp, Dn 38, 400 Mbh Polidoro 350.0970.03	3
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
	500	111544-02	Kit includes:
106096-01		1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	1
107694-01		O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	1
108161-01		Warning Card, Blower Outlet Gasket Installation	1
110301-01		Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
110502-01		M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	1
111054-02		Mixer, Lamp500, Hm150 Lp, Dn 42-44, 12:00 Polidoro 350.0971.06	3
112068-11		Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
81960109		Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
650		111544-03	Kit includes:
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	110056-02	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
	110202-01	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110501-03	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	1
	111054-03	Mixer, Lamp650, Hm500 Lp, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.05	4
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
	800	111544-04	Kit includes:
108161-01		Warning Card, Blower Outlet Gasket Installation	1
110056-02		Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
110202-01		O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
110301-01		Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
110501-03		M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	1
111054-04		Mixer, Lamp800, Hm500 Lp, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.03	4
112068-11		Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
81960109		Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1
1000L		111544-05	Kit includes:
	108161-01	Warning Card, Blower Outlet Gasket Installation	1
	110056-02	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	1
	110202-01	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	1
	110301-01	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	1
	110501-03	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	1
	111054-05	Mixer, Lamp 1000, Hm500 Lp, Dn 55, 1000Mbh, 140Bc Polidoro	4
	112068-11	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	1
	81960109	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	1

1000-4000 NO Conversion Kit Required. Refer to I&O Manual for Instructions, Setting and Details.