



# AMP GAS CONVERSION KITS

Field Conversion Kits: To Natural Gas				Field Conversion Kits: To LP Gas			
MODEL	KIT NUMBER To Natural Gas	Description	List	MODEL	PART NUMBER To LP Gas	Description	List
<b>400</b>	<b>111545-01</b>	<b>Kit includes:</b>	<b>\$181.00</b>	<b>400</b>	<b>111544-01</b>	<b>Kit includes:</b>	<b>\$181.00</b>
	1	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard			1	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	
	1	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark			1	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	
	1	Warning Card, Blower Outlet Gasket Installation			1	Warning Card, Blower Outlet Gasket Installation	
	1	Mixer, Lamp 400, Hm140 Ng, Dn 38, 400 Mbh Polidoro 350.0970.02			1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	
	1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp			1	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	
	3	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148			3	Mixer, Lamp 400, Hm140 Lp, Dn 38, 400 Mbh Polidoro 350.0970.03	
	1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx			1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	
	1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)			1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	
<b>500</b>	<b>111545-02</b>	<b>Kit includes:</b>	<b>\$190.00</b>	<b>500</b>	<b>111544-02</b>	<b>Kit includes:</b>	<b>\$190.00</b>
	1	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard			1	1" Water Gasket 1.18 Od X .06 Thick Garlock Blue Gard	
	1	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark			1	O-Ring, 3" Od X 2-3/4" Id For Ra148 Blower Venturi, 320/399 Mbh, Orange Mark	
	1	Warning Card, Blower Outlet Gasket Installation			1	Warning Card, Blower Outlet Gasket Installation	
	1	Mixer, Lamp500, Hm150 Ng, Dn 42-44, 12:00 Polidoro 350.0971.04			1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	
	1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp			1	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148	
	3	M4 X 0.7, 12Mm Long Socket Head Screw McMaster Pn: 91290A148			3	Mixer, Lamp500, Hm150 Lp, Dn 42-44, 12:00 Polidoro 350.0971.06	
	1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx			1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	
	1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)			1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	
<b>650</b>	<b>111545-03</b>	<b>Kit includes:</b>	<b>\$443.00</b>	<b>650</b>	<b>111544-03</b>	<b>Kit includes:</b>	<b>\$443.00</b>
	1	Warning Card, Blower Outlet Gasket Installation			1	Warning Card, Blower Outlet Gasket Installation	
	1	Mixer, Lamp 650, Hm500 Ng, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.04			1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	
	1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000			1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	
	1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer			1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	
	1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp			1	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	
	4	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418			4	Mixer, Lamp650, Hm500 Lp, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.05	
	1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx			1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	
	1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)			1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	
<b>800</b>	<b>111545-04</b>	<b>Kit includes:</b>	<b>\$443.00</b>	<b>800</b>	<b>111544-04</b>	<b>Kit includes:</b>	<b>\$443.00</b>
	1	Warning Card, Blower Outlet Gasket Installation			1	Warning Card, Blower Outlet Gasket Installation	
	1	Mixer, Lamp 800, Hm500 Ng, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.02			1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	
	1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000			1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	
	1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer			1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	
	1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp			1	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	
	4	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418			4	Mixer, Lamp 800, Hm500 Lp, Dn 50, 140 Bc, 12:00 Polidoro 350.0973.03	
	1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx			1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	
	1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)			1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	
<b>1000L</b>	<b>111545-05</b>	<b>Kit includes:</b>	<b>\$443.00</b>	<b>1000L</b>	<b>111544-05</b>	<b>Kit includes:</b>	<b>\$443.00</b>
	1	Warning Card, Blower Outlet Gasket Installation			1	Warning Card, Blower Outlet Gasket Installation	
	1	Mixer, Lamp 1000, Hm500 Ng, Dn 55, 1000Mbh, 140Bc Polidoro			1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000	
	1	Gasket, Polidoro Mixer To 1" Npt Adapter Lamp 650-1000			1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer	
	1	O-Ring, 110Mm Id, 117 Od 3.5 Mm Width Blwr To Mixer			1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp	
	1	Label Sheet, Natural/Lp Gas Conversion Label Amp/Lamp			1	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418	
	4	M8 X 1.25, 16Mm Long Button Head Hex Screw McMaster 91239A418			4	Mixer, Lamp 1000, Hm500 Lp, Dn 55, 1000Mbh, 140Bc Polidoro	
	1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx			1	Instructions, Gas Valve Mixer, 400-1000L Amp/Bfit/Ctd/Phx	
	1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)			1	Label, 2" X 4", L6003025p Duratran Ii Top Coated Paper (Itermec E18235)	
<b>1000-4000</b>	<b>NO KIT REQUIRED.</b> Field conversion accomplished via gas valve adjustment. Please consult I&O Manual for full instructions and details.						